

## Hawiflex® EasiFix solves noise and abrasion problems

**The Challenge:** Transfer of oversize material in a busy sand and gravel plant was causing significant noise problems. Hard, rigid polyethylene wear liners magnified noise levels. Impact damage caused premature failure leading to costly regular replacement.



**Our Solution:** Hawiflex® EasiFix polyurethane lining with integral foam backing

**Key Features:** High elasticity polyurethane with foam backing cushions impact  
Adhesive friendly for quick, safe installation

**Improvement:** Oversize transfer chute virtually silent when in production  
Wear life increased by 300% and still operational

**Benefits:**

- Environmental** - dramatic reduction in noise levels
- Efficiency** - 'trampoline' effect promotes material flow for fewer blockages
- Installation** - adhesive friendly foam reduces fitting time and cost
- Productivity** - low noise enables production over longer working day
- Competitive** - lowest cost per tonne

*“When we first installed EasiFix, it caused such a reduction in noise levels we thought the plant had broken down. In fact, it was running, but the chute was almost silent. It is also holding up very well against wear and tear.” Plant Manager*

