


## Table liner adjustment made a thing of the past: Vibration Table Liners

**The Challenge:** A leading manufacturer's vibration table liners on a concrete block machine producing high quality dense blocks were experiencing severe abrasion. The case hardened steel liners were struggling to cope with the demands of high volume production and had a service life of just 10-12 weeks before requiring approximately 5 hours of adjustments.



**Our Solution:** ConSpareUltra tungsten carbide protected vibration table liners

**Key Features:** Highly abrasion-resistant, equivalent to 90+Rockwell

**Improvement:** **Case hardened steel:** 5 hours of adjustment every 3 months  
**UltraTungsten:** No adjustment in over 12 years and still operational

**Benefits:** **Productivity** - over 260 maintenance hours saved and maintenance hotspot eliminated, increasing production time  
**Safety** - less maintenance in a confined space required  
**Quality** - Blocks produced are even more consistent with greater dimensional accuracy

*"The performance of our tungsten table liners is outstanding. We are a high production plant and it is remarkable that, after 12 years operation, there are no signs of wear at all. The tungsten copes well with such a harsh environment and has never cracked. We have saved hundreds of hours of downtime. I cannot recommend them highly enough."*  
Works Manager

