

## High impact Twinshaft mixer cleaning: Walter Washout System

**The Challenge:** A high volume readymix concrete plant was plagued with problems caused by rapid build up of hardened concrete in their twinshaft mixer. Other washout systems failed to make any impact so the decision was taken to install a specially developed Walter system.



**Our Solution:** Walter DAB double pump twinshaft cleaning system

**Key Features:** High pressure combined with increased water volume  
Water jet maintains penetration over larger cleaning area

**Improvement:** Mixer cleaned to 95% of new

**Benefits:**

- Safe** - entry to mixing trough minimised
- Quality** - mix quality and consistency improved
- Productivity** - less downtime = more production
- Cost Effective** - spares spend reduced
- Staff** - better working conditions
- Wear Parts** - no hammers for cleaning, no breakages

*“Ours was a difficult challenge and other systems had failed. We were sceptical whether the Walter system could cope but decided to give it a go. I have to admit we are very impressed with the cleaning performance. The design of the double pump system is very clever and the extra power means it is man enough for the job.”* Engineering Manager

