


Table liner adjustment made a thing of the past: Vibration Table Liners

The Challenge: A leading manufacturer's vibration table liners on a concrete block machine producing high quality dense blocks were experiencing severe abrasion. The case hardened steel liners were struggling to cope with the demands of high volume production and had a service life of just 10-12 weeks before requiring approximately 5 hours of adjustments.



Our Solution: ConSpareUltra tungsten carbide protected vibration table liners

Key Features: Highly abrasion-resistant, equivalent to 90+Rockwell

Improvement: **Case hardened steel:** 5 hours of adjustment every 3 months
UltraTungsten: No adjustment in over 12 years and still operational

Benefits: **Productivity** - over 260 maintenance hours saved and maintenance hotspot eliminated, increasing production time
Safety - less maintenance in a confined space required
Quality - Blocks produced are even more consistent with greater dimensional accuracy

"The performance of our tungsten table liners is outstanding. We are a high production plant and it is remarkable that, after 12 years operation, there are no signs of wear at all. The tungsten copes well with such a harsh environment and has never cracked. We have saved hundreds of hours of downtime. I cannot recommend them highly enough."
Works Manager

